

	PAGE
Iron and steel classification; names and apparatus in which	
generally made	440, 441
, definitions of the different varieties	442 to 447
, general classification of	166, 167
, heat-treatment of	165
, increase in production of	380 to 383
, magnetic properties of	447, 448
, manufacture, cost of	380, 381
, metallography of	160 to 217, 475
, microscopic constituents of	174 to 182, 475
, progress in the manufacture of	313 to 383
, statistics . 313 to 315, 342 to 345, 347, 349, 361, 363, 366, 380 to 383	
, structure of	242 to 267
, their prominent uses	186, 187
, basic Bessemer, composition of	327
, beta	216
Iron-carbon compounds, allotropic states in the	214 to 216
, constitution of the	184, 185
, freezing-point curves of	193 to 208
, graphito-pearlite series of	188, 189
, reactions in freezing and transformation of the	197 to 203
, Roberts-Austen's diagram of the	192, 194
, scheme of definitions for the . 170, 171, 442 to 447	
, the austenite series of	191
, the pearlite series of	184, 188, 189
, transformation curves of the	193 to 214
, eutectic of phosphoric	33
, gamma	216
, its extraction from its ores	330 to 343
, manufacture, the general scheme of	325 to 329
, wrought, manufacture of	343 to 347
Irreversibility	290, 291
Isomorphous mixtures (see solid solutions)	11
J	
"Jog" of cooling curves, the	28
Johnson, J. E., Jr., on conditions within the blast-furnace	385
on critical temperature in the blast-furnace process	473
Jones's mixer	357
K	
Kennedy hot-blast stove	340, 341
-Morrison rail-rolling process, the	266

	PAGE
Kourbatoff on the hardness of austenite and martensite	183
Krupp carburizing process, the	325
L	
Lag	195, 289 to 292
, deformations of the cooling curves by	218
Laws concerning fracture and temperature, general	245 to 252, 264
Lead-tin alloys	43
, cooling curves of	60
, electric conductivity of	156
, electromotive force of	159
, freezing-point curve of	54, 55, 60, 61
Ledebur on carbide-carbon	176
temper-carbon	181
Lime-alumina silicates, heat of solidification of	403
Linings of converters, life of	364
M	
Macroscopic segregation	101, 106
Magnetic properties of iron and steel	447, 448
Malleable castings, the manufacture of	281
Malobservation in recording cooling curves	20
Management of the blast-furnace, the metallurgical	392
Manganese, its influence on blowholes and pipes	370
retards the transformation of austenite steel	178
Manufacture of iron and steel, progress in the	317, 320 to 323
, the cost of	313 to 383
malleable castings, the	380, 381
steel, the	281
wrought iron	347 to 366
.	343 to 347
Martensite	179, 180, 475
Materials, for the blast-furnace, the handling of raw	331
"Matrix," definition of the term	431, 432
Mechanical refining of steel	262 to 267
treatment of ingots	366 to 380
Metallography of iron and steel, the	160 to 217, 475
Metals, chemical compounds among	8
, microscopic examination of	14
, their resemblance to the crystalline rocks	3
Methods of treating sections for microscopic examination	16
study of the constitution of alloys	13
Microscopic constituents of iron and steel, the	174 to 182, 475
constitution of irons and steels	186, 187
the pearlite series	162
various steels	161, 162

	PAGE
Microscopic examination of alloys	14
segregation	101
Microstructure of a bismuth-tin alloy	32
austenite	180
a copper-aluminium alloy	48, 88
copper-tin alloy	72
alloys of limited reciprocal solubility	70
burnt steel	258
cast iron	92
copper-silver alloys	46 to 49
gray cast iron	164, 432
hypo-eutectoid steel	50
martensite	180
steel, effect of T_{max} on the	250
(high-carbon)	180
, influence of finishing temperature on	265
quenching temperature on	224
the pearlite series	opp. 188
tin-antimony alloys	46, 89
white cast iron	48, 432
wrought iron	169
Mixed crystals (see solid solutions)	11
Mixer, the	357
Mixtures, Isomorphous (see solid solutions)	11
Molybdenum steel	325
Mond gas producer	453 to 457
Monell process, the	356
Morgan's continuous heating furnace	377, 378
Mother-liquor and mother-metal, definition of	19
Mottled cast iron	168
Mould car for the car-casting system	359

N

Neilson, his invention of the hot-blast	473
Nickel retards the transformation of austenite	178
steel	316 to 319
Nomenclature of the iron-carbon compounds	170, 171, 173, 442 to 447

O

Open-hearth process	347 to 356
, modification of the	354 to 356
Osmond on austenite	177, 178
the hardness of austenite and martensite	180
magnetic properties of iron	447

	PAGE
Osmond, photograph of martensite	180
in austenite	180
pearlite	177
Osmond's methods for polishing metallic sections	17

P

Pearlite	176, 475
series, microscopic constitution of the	162, 184, 185
of the iron-carbon compounds	188, 189
, physical properties of the	162
Phase rule	283 to 313
, application of the	311
, examples testing the	300 to 311
, its value to metallurgists	285
quantitative not qualitative, the	311 to 313
, terminology of the	293 to 297
: the formula	300
Phases, examples of: the phase rule	294 to 297
Phosphoric iron, eutectic of	33
Phosphorus, its removal in the open-hearth process	349
Physical actions: the phase rule	298
properties of carbon steels	322, 323
manganese steels	320 to 323
nickel steels	318, 319
steel, influence of quenching on the	224, 225
, influence of T_{max} on the	267 to 276
the pearlite series	162
Pietzka puddling furnace, the	345
Pig and ore process	354
scrap process	354
-casting machine, Uehling's	335, 336
Pipes	366 to 368
, Sauveur's process for the prevention of	368
Presses, hydraulic	379
Price of certain products, reduction in	380, 382
Process, basic Bessemer	362 to 364
open-hearth	349, 356
, Bertrand-Thiel	355
, Bessemer	356 to 364
, blast-furnace	330 to 343
, Darby's recarburizing	364
for the prevention of pipes, Sauveur's	368
, Gayley dry-blast	457 to 475
, modifications of the open-hearth	354 to 356
, Monell	356
, open-hearth	347 to 356
, pig and ore	354

	PAGE
Process, pig and scrap	354
, puddling	344 to 347
, Siemens-Martin	347 to 356
, Talbot	355
Processes, comparison of steel	365
for compressing ingots for the prevention of pipes	373, 374
, Harvey and Krupp carburizing	325
of iron manufacture, classification of	329
Producer, the Duff gas	428, 429
, the Mond gas	453 to 457
, the Siemens gas	423 to 425
, the Taylor gas	425 to 428
, the use of steam in the gas	429
Production in the blast-furnace, increase in the rate of	342
open-hearth process, increase in the rate of	347
, maximum, by a pair of American converters	361
of iron and steel, increase in	380 to 383
wrought iron, decline in the	344
Progress in the manufacture of iron and steel	313 to 383
Properties of cast iron of 4% carbon	437 to 440
the allotropic states in the iron-carbon com- pounds	215
eutectic	31 to 35, 38 to 43
pearlite series, physical	162
Pseudomorphic crystal, definition of	51
Puddling furnace, comparison of the Roe with the Danks and the Pernot	451, 452
, direct-fired reverberatory	410
, the Pietzka	345
, the Roe	449 to 453
process, the	344 to 347
Purifying processes of iron manufacture	330
Q	
Quenching, its influence on the hardening of steel	223 to 230
temperature, its influence on the properties of steel	224
R	
Rail-rolling process, the Kennedy-Morrison	266
Rapidity of cooling on segregation, effect of	102 to 112
Rate of production in the blast-furnace, increase in the	342
, in the open-hearth process, increase in the	347
Raw materials for the blast-furnace, the handling of	331
Reactions in freezing and cooling of typical cast irons	277 to 279

	PAGE
Reactions in freezing and transformation of the iron-carbon compounds	197 to 203
the blast-furnace	387, 391 to 395, 405
Recalescence	219
, loss of the hardening power at the	235
Recarburizing process, Darby's	364
Recuperative and regenerative furnaces, comparison of	416, 417
Regeneration, the value of gas	418 to 422
Regenerative and recuperative furnaces, comparison of	416, 417
furnaces, the rise of temperature in	422
Relief-polishing method for preparing metallic sections	17
Removal of phosphorus in the open-hearth process	349
Reversibility	289 to 292
Richards, Professor J. W., his study of the dry-blast process	468
Roberts-Austen's diagram of the iron-carbon compounds	192, 194, 197 to 214
Roe's puddling furnace	449 to 453
Rolling-mill, continuous	378
S	
Salt-water, cooling curves of	18, 29, 30
freezing-point curve	58
Saniter develops the structure of austenite	179
Saturation-point curve, its position under various conditions	119 to 133
, its relation to the freezing-point curve	119 to 133
of mercuric bromide and iodide	118
molten binary alloys	117
curves	116 to 147
, determination of	133 to 135
Sauveur, Albert, on classification and definitions of iron and steel	440
on the constitution of the iron-carbon compounds	184, 185
Sauveur's process for the prevention of pipes	368
Scheme of iron manufacture, the general	325 to 329
Segregation	86 to 88, 99 to 116
, effect of diffusion on	100
, effect of freezing on	102 to 112
in steel ingots	372
, microscopic	97
Selective freezing	24, 26, 28, 65, 135, 139 to 147
Self-hardening steels, composition of	324
Series, austenite, of iron-carbon compounds	191
, gray cast iron, of iron-carbon compounds	188, 189
, pearlite, of iron-carbon compounds	184, 188, 189
, uses of the austenite	192
Shaping processes: iron manufacture	330
Siemens furnace, the	350 to 353

	PAGE
Siemens gas producer, the	423 to 425
Siemens-Martin process, the	347 to 356
Silicates, lime-alumina, heat of solidification of	403
Silicon-content of cast iron, effect of reduction in the blast-furnace on the	397
, its influence on blowholes and pipes	370
the formation of graphite	208, 209
Silver-copper alloys, electric conductivity of	157
microstructure of	46 to 49
on the structure of eutectic of	41
-gold alloys, electric conductivity of	155
, freezing-point curve of	67
Size of converters, range in	361
Slag, composition of basic Bessemer	364
, effect of deoxidation on the lime-content of blast-furnace	405
melting-point, its influence on hearth temperature	399 to 401
, regulation of the melting-point of blast-furnace	402
: wrought iron	164, 181
Slags, composition of iron blast-furnace	403
Soaking pit, Gjers	375 to 376
Solid solution alloys, eutectic of	66, 67
type of alloys	64 to 68
solutions	9, 10
, electric conductivity of	154
, heterogeneousness of	13, 66, 88
Solubility, effect of temperature on	115
Sorbite	181, 475
Sorby's method of etching: simple attack	16
Spherulitic structure of eutectics, reasons for	41 to 43
St. Etienne process of compressing ingots, the	374
Statistics, iron and steel . 313 to 315, 342 to 345, 347, 349, 361, 363, 366, 380 to 383	
Stead's brittleness	255
Steam in the gas producer, the use of	429, 453 to 456
, its use in the Mond gas process	453 to 456
Steel and iron, boundary between	447
classification; names and apparatus in which	
generally made	440, 441
, definitions of the different varieties	442 to 447
, general classification of	166, 167
, heat-treatment of	165
, increase in production of	380 to 383
, magnetic properties of	447, 448
manufacture, cost of	380, 381
, progress in	313 to 383
, metallography of	160 to 217, 475

	PAGE
Steel and iron statistics . 313 to 315, 342 to 345, 347, 349, 361, 363, 366, 380 to 383	
, structure of	242 to 267
, annealing of hardened	231
, chrome	323
, composition of basic Bessemer	327
Taylor-White	324
typical kinds of	172
, constitution of hardened	164
slowly cooled	184
, conversion into	347 to 366
, cooling curve of high-carbon	220
, effect of the rate of cooling on the hardening of	234, 235
, explanation of the tempering and annealing of	231 to 234
, hardening and tempering of	221 to 240
, heat-refining of	242, 251 to 262
, heat-treatment of	217 to 282
, influence of quenching on the hardening of	224, 225
ingots, defects in	366 to 373
, "draft" fluid compression of	373
, pipes and blowholes in	366 to 373
, segregation in	372
, manganese	317, 320 to 323
, manufacture of	347 to 366
, microstructure of	50, 177, 180, opp. 188, 258
burnt	258
hypo-eutectoid	50
, molybdenum	325
, nickel	316 to 319
processes, comparison of	365
, physical properties of	162
, stress in	236 to 240
, tempering of hardened	230
, transformations of	227 to 230
, tungsten	324
Steels, alloy	165, 316 to 325
and irons, their prominent uses	186, 187
, composition of self-hardening	324
Stoichiometric calculations	182, 183
Stoves, hot-blast	338 to 342
Stress in steel	236 to 240
Stratification according to density	44, 45
Structure, its relation to the fracture	244
of austenite, laws concerning the	246 to 248
iron and steel, the	242 to 267
the eutectic	32, 38, 39, 41 to 43

	PAGE
Sulphur-content of cast iron, effect of deoxidation in the blast-furnace on the	397
, the transformations of	225 to 227
Surfusion	20, 35 to 38, 54 to 57

T

Talbot process, the	355
Taylor gas producer, the	425 to 428
-White steel, composition of	324
Temper-carbon	181
-graphite	181, 282
Temperature and fracture, general laws concerning	245 to 252, 264
grain-size, relation between	246 to 257, 262 to 267
-composition curves	135 to 147
, hearth, of the blast-furnace	398 to 401, 406
, heat-refining	255
, initial, its influence on utilization of heat	460 to 475
in regenerative furnaces	422
, its effect upon brittleness	259
, maximum, its influence on the physical properties of steel	267 to 276
of escaping gases a measure of heat utilization	460
, quenching; its relation to the hardening of steel	223
Temperatures, critical, of steel	20, 194, 214 to 217
Tempering of steel, the	221, 230, 231
Tensile strength of manganese steels	320
nickel steels	318
steel, influence of T_{max} on the	274 to 276
Terminology of the phase rule	293 to 297
Thermo-electric method of recording cooling curves	22
power	154
Tilting furnace	352 to 354
Tin-antimony alloys, microstructure of	46, 89
-bismuth alloy, microstructure of a	32
alloys, freezing-point curve of	75
, cooling curve of	35
-copper alloy, cooling curve of	37
, microstructure of	72
-lead alloys	43
, electric conductivity of	156
, electromotive force of the	159
, freezing-point curve of	54, 55, 60, 61
Transformation-curves of the iron-carbon compounds	193 to 214
, reactions in, of the iron-carbon compounds	197 to 203
Transformations of steel, the	227 to 230
sulphur, the	225 to 227

	PAGE
Transition stages between austenite and pearlite, note on	475
Troostite	180, 475
Tungsten steel	324

U

Uehling's pig-casting machine	335, 336
Unselective freezing	28
Uses of the austenite series of the iron-carbon compounds	192
, prominent, of the various irons and steels	186, 187

W

Walrand-Legenisel modification of the Bessemer process	362
Water-cooling blocks, Gayley's	336, 337
Wellman charging system, the	354
Wellman's tilting furnace	354
Weyl's method of attack for metallic sections	16
White cast iron, constitution of	163
White cast iron, genesis of	435 to 437
Whitwell hot-blast stove	339, 340
Whitworth process of compressing ingots, the	373
Wright, C. R. A., method for determining saturation-point curves	134
Wrought iron, constitution of	164
, decline in the production of	344
, definition of	447
, fracture of barked	243
, its distinctive properties	168 to 170
, manufacture of	343 to 347
, microstructure of	169
Wood's car-casting system	358 to 361

